

Fire at Waste Paper Facility



ILC Assignment:

- Site inspection of the fire-damaged equipment in the insured's facility.
- Assess the condition of equipment and determine repair versus replacement costs.
- If restorable, determine the scope of work to be completed and the timeframe.

ILC Analysis:

- ILC thoroughly inspected the various damaged equipment to determine if it was restorable to pre-loss condition.
- Photographic records and documentation of the loss and damage were gathered.
- During the inspection, ILC witnessed extensive damages to the sorting line caused by heat and the partial collapse of the roof.
- ILC obtained the cost of the replacement sorting line from the OEM totaling \$3.2 million.

Summary:

- ILC's thorough inspection of the insured loss revealed that the sorting line did not cost or time-efficient to repair.
- LKQ replacement parts were sourced and ILC confirmed the equipment could not be repaired.